	Туре	L#	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	110175	"290"/\$.ccls. or "322"/\$.ccls. or "310"/\$.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:30
2	BRS	L2	36412		US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:31
3	BRS	L3	13785	2 and axis	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:31
4	BRS	L4	2729	3 and gear	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:31

	Туре	L#	Hits	Search Text	DBs	Time Stamp
5	BRS	L5	1083	4 and "permanent magnets"	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:32
6	BRS	L6	789	5 and coils	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:32
7	BRS	L7·	624	6 and plurality	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:32
8	BRS	L8	578	7 and rotation	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:33

	Туре	L#	Hits	Search Text	DBs	Time Stamp
9	BRS	L9	388		US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:33
10	BRS	L10	312	9 and electrical	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:42
11	BRS	L11	125	10 and vertical	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:34
12	BRS	L12	151	10 and (hand or manual)	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/04/19 16:42